





TS 5000 Eline
TS 5000 S Eline



144856-03

GEZE




5 mm


A

















$a \leq 1250 \text{ mm}$




B




$a \leq 1250 \text{ mm}$




1




2




3






4







5



6





7





i+



TS 5000 S



8



i

 $a \leq 1250 \text{ mm}$  $a \leq 1250 \text{ mm}$  $a > 1100 \text{ mm}$ 